25X1∙	•	Approved For Release இழ் இழு	25X1
NRO	REVIEW	COMPLETED  Copy 5 of 11  26 October 1967	
MEN	MORAND	OUM FOR THE RECORD	
SUB	JECT: (	Critique for OXCART Mission Number BX6729	
OSA	Control	sion critique of Mission Number BX6729 conducted in the Center at 0930 hours, 25 October 1967.	
25X1	2. Mis  a. b. c. d. e. f. g. h.  i. i. m.	Mission Number: BX6729 Date Flown: 18 Oct 1967 Area of Operation: North Vietnam Mission Success: Successful Pilot's Name: Aircraft Number: 129 Primary or Spare Flown: Primary Take-off Time - Planned: 0115Z Actual: 0222Z Landing Time - Planned: 0506Z Actual: 0623Z Time Enroute - Planned: 3+51 Actual: 4+01 Departure Base: Kadena AB Landing Base: Kadena AB Equipment:  (1) Primary: Type I,  (2) Spare: Same as primary.	25X1
			25X1
25X1		Approved: For SECRET	

25X1

25X1

Page 2

- 3. Operations:
  - a. Route (INS Plot vs Planned): Satisfactory
  - (1) Comments: Fuel option taken due to inlet problem and marginal weather at Kadena.
    - (2) INS Terminal Error:

25X1

(3) INS Spec Error:

- b. Mission Generation & Operational Support: Satisfactory
  - (1) Comments:
    - (a) Original take off delayed 48 hours due to Typhoon "Carla".
  - (b) Take off delayed 1+07 due to heavy rain shower over Kadena at 0115Z.
- c. Other comments: Recovery weather 600 broken, 1 1/2 miles visibility in rain. Strip alert tanker launched in case of further weather deterioration and/or a missed approach.
- 4. Weather:
  - Forecast vs Actual:
    - (1) As briefed.

25X1

(2) Comments: Catagory II or better forecast. \_\_\_\_\_\_reported cloud cover as 5%. Pilot experienced moderate-severe turbulence over Typhoon "Carla" (at 77M). Terminal weather at Kadena was marginal.

25X1

Page	3	

- b. Weather Scout Reporting: Satisfactory
- 5. Intelligence;
  - a. Target Coverage:
    - (1) 24 of 24 programmed targets covered.
    - (2) 8 first priority SSM targets of 9 covered.
    - (3) 19 of 27 first priority NVN COMOR targets covered.
    - (4) 153 SAM sites, 16 sites occupied, 1 new site.
    - (5) 16 other priority NVN COMOR targets covered.
  - (6) Comments: Mission was very productive. Western and northwestern part of North Vietnam that have generally been cloud covered were photographed. The Lao Cai rail yards were approximately 25% filled. No build up of supplies or equipment observed. Photography on the Dien Bien Phu area revealed no SAM or other unusual activity. Most of the rail lines north of the panhandle were covered.
  - b. Quality of Take: Satisfactory
    - (1) Resolution: Good
  - (2) Camera Operation: NPIC reported possible Camera malfunction during evaluation of dupe. Evaluation of original negative indicated actual problem to be quality control in preparation of duplications. DIA to take corrective action.

ı	
ı	
ı	
ı	
ı	
ı	
	,
	4

25X1

25X1

25X1

Approved For Release 2002/08/20 : CIA-RDP69B00404R000100210001-1

TOP SECRET

	Approved Fee Release 2002/08/29 : CIN RDP69B00404R000100210001-1	
	Page 4	2
	f. Take Movement:	
	(1) Photography: Satisfactory	
6.	Materiel:	
	a. Aircraft General: Satisfactory	
	(1) Comments: Right engine spike hammered continuously on second leg over denied. Left engine spike hammered slightly near end of mission. Auto pilot porpoised on second leg over denied	ı.
	b. Aircraft Systems: Satisfactory	
7.	Communications: Satisfactory	
	a. Message Traffic: Satisfactory	
	b	
	c. UHF/HF Commo: Satisfactory	
8.	Outstanding Action Required:	
(Int	a. D/SA requested photo of storage-training area at Thai Nguyen elligence Division, OSA).	
	•	
aver	c. ChiCom altitude reports listed on briefing charts should reflect rage altitude at exit denied. Also, suggested that reported vs actual reported on chart (Intelligence Division, OSA).	J
		25

TOP SECRET

25X1

Page 5

- d. Verify corrective action by DIA listed para 5 b (2) (Sensor Systems Division, OSA).
- e. Investigate reported milk effect on left windshield after rain repellant used on final approach (Deputy for Materiel, OSA).
- f. Request Lockheed assist in analysing current engine inlet problems such as encountered on this mission (Deputy for Materiel, OSA).

25X1

Deputy for Operations, OSA

25X1

OXC/O/OSA DISTRIBUTION:

#1 - D/SA

#2 - D/O/OSA

#3 - D/M/OSA

#4 - D/R&D/OSA

#5 - OXC/O/OSA

#6 - Intel/O/OSA

#7 - Wea/O/OSA

#8 - Commo/O/OSA

#9 - ADP/O/OSA #10- RB/OSA

#11 - CHRONO

25X1

Approved For Release 2002/08/20 : CIA-RDP69B00404R000100210001-1